Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, Michigan 48239-4001
Telephone: 313-592-5000

June 26, 2014

ALASKA STATE OF DOT
2200 E 42ND AVE
ANCHORAGE AK 99508

Subject: Field Action 14W1
GHG14 DD Platform Software Reprogramming

Detroit Diesel Corporation (DDC) has determined that some certified GHG14 DD platform engines will require software and fuel maps to be reprogrammed on affected engines in order to prevent fault codes and performance issues that may result in customer dissatisfaction.

Records available to us indicate that your vehicle has one of the eligible engines.

Instructions for this Field Action have been sent to your local Detroit Diesel Authorized Repair Facility and the labor time required to perform this software update is approximately **1.0** hour.

Please contact a Detroit Diesel Authorized Repair Facility to arrange to have the Field Action performed. To locate an authorized facility, search online at www.detroitdiesel.com/locations/default.aspx.

This service will be completed for you at no charge, prior to **June 26, 2015**, under the provisions of this notice.

DETROIT DIESEL
FIELD ACTION 14W1
SERVICE ADMINISTRATION CAMPAIGN COORDINATOR (BX-5)

Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, Michigan 48239-4001
Telephone: 313-592-5000

ALASKA STATE OF DOT

Engine Serial Number	VIN
471927S0175983	1FVHG3DV8EHFH6503
471927S0175976	1FVHG3DV6EHFH6502